

CROWN MOTORS LTD.

皇冠汽車有限公司
22/F, Citicorp Centre
18 Whitfield Road
North Point, Hong Kong
Tel : (852) 2562 2226
Fax: (852) 2811 1060

Press Release

20th April, 2010
(Released at 10:00am)

Toyota Motor Corporation Announces
Recall of Left-Hand Drive Land Cruiser Prado,
Hong Kong Not Affected

Toyota Motor Corporation (TMC) has announced a recall of the Land Cruiser Prado in certain left-hand drive countries. After receiving this news, Crown Motors Limited (CML) was in immediate contact with TMC and was confirmed that Hong Kong is not affected. The left-hand drive model is different from the right-hand drive which has been sold in Hong Kong, for example they have various weight distributions and Vehicle Stability Control (VSC) mechanisms. CML has received NO related complaints or accident reports.

The manufacturer in Japan has made this recall due to an update in the VSC software. The system uses computers linked to sensors to detect when the car starts to drift in turns and then applies more brake power or less engine power to keep the vehicle on track. The VSC provides extra safety protection for the driver and passengers, but it is not essential for the operation of the vehicle.

For media enquiries, please contact:

Mr. Sam Lee

Crown Motors Ltd.

Tel: 2880 1361

Fax: 2887 2787

Email: sam.lee@inchcape.com.hk