



**Crown Motors Ltd.**  
22/F., Citicorp Centre,  
18 Whitfield Road,  
North Point, Hong Kong

Press Release

19th May 2010

(Released at 6 pm)

## **News Reports on the Steering of Lexus LS460 and LS600hL**

According to Toyota Motor Corporation (TMC), a situation has occurred on Lexus LS460 and LS600hL model vehicles. When the vehicle completes a turn and resumes back to its central position, there is a possibility that the steering wheel angle may slightly deviate from the central position, whereas both front wheels remain in a straight-line position. The situation is now under investigation. Crown Motors Ltd. (CML) will keep close communication with the manufacturer on the progress and will make immediate announcements with any updated news.

Since the launch of Lexus LS series in the second half year of 2006, CML has received NO related customer complaints or accident reports.

For enquiries, please contact our Customer Care Hotline at 2880 1395.

### **For media enquiries, please contact:**

Ms. Yen Leung

Crown Motors Ltd.

Tel: 28801357

Fax: 28872787

Email: [yen.leung@crown-motors.com](mailto:yen.leung@crown-motors.com)

#### **Premium Outlets:**

Shop A, G/F Harcourt House,  
39 Gloucester Road,  
Wanchai, Hong Kong  
Tel: (852) 2511 9430  
Fax: (852) 2507 2654

G/F Mita Centre,  
552-566 Castle Peak Road,  
Kwai Chung, New Territories  
Tel: (852) 2880 4151  
Fax: (852) 2413 2971

#### **Service centres:**

Block B & C, G/F Seaview Estate,  
2-8 Watson Road,  
North Point, Hong Kong  
Tel: (852) 2880 1551  
Fax: (852) 2960 1354

G/F Mita Centre,  
552-566 Castle Peak Road,  
Kwai Chung, New Territories  
Tel: (852) 2880 4900  
Fax: (852) 2413 2971

