



Crown Motors Ltd.
22/F., Citicorp Centre,
18 Whitfield Road,
North Point, Hong Kong

Press Release

21st May 2010

Announcement for Recall of Lexus LS460 and LS600hL

As confirmed with the manufacturer in Japan, Crown Motors Ltd (CML) will carry out a recall on the Lexus LS460 and LS600hL models (those of factory year from September 2009 to May 2010). This recall will affect around 50 vehicles sold in Hong Kong.

The recall is due to a problem with the electronic control system. The steering wheel may over-rotate when the driver returns it to the centre position after turning it sharply to the left or right for several seconds, whereas the car remains moving straight ahead. CML will follow factory guidelines and make the correct adjustments, replacing the steering wheel's electronic control components. CML is now in contact with the affected owners.

CML has sold over 750 Lexus LS460 and LS600hL model vehicles since launch, no such complaint or accident report has been received regarding this issue.

For enquiries, please contact our Service Centers or Service Hotline at 2880 4130.

For media enquiries, please contact:

Mr. Samuel Lee

Crown Motors Ltd.

Tel: 2880 1361

Fax: 2887 2787

Email: sam.lee@inchcape.com.hk

Premium Outlets:

Shop A, G/F Harcourt House,
39 Gloucester Road,
Wanchai, Hong Kong
Tel: (852) 2511 9430
Fax: (852) 2507 2654

G/F Mita Centre,
552-566 Castle Peak Road,
Kwai Chung, New Territories
Tel: (852) 2880 4151
Fax: (852) 2413 2971

Service centres:

Block B & C, G/F Seaview Estate,
2-8 Watson Road,
North Point, Hong Kong
Tel: (852) 2880 1551
Fax: (852) 2960 1354

G/F Mita Centre,
552-566 Castle Peak Road,
Kwai Chung, New Territories
Tel: (852) 2880 4900
Fax: (852) 2413 2971



Inchcape