



**Crown Motors Ltd.**  
22/F., Citicorp Centre,  
18 Whitfield Road,  
North Point, Hong Kong

Press Release

1<sup>st</sup> July, 2010

*(Released at 7:30pm)*

**A Recall for Some of the Lexus LS & LSh in Hong Kong is needed**  
**Other Lexus Models are NOT Affected**

Crown Motors Limited (CML) announces that some of the Lexus LS460 and LS600h sold in Hong Kong needed to be recalled. The number of involved vehicles is about 660, whereas **other Lexus models sold in Hong Kong are not affected.** The recall of LS and LSh series is due to the existence of impurities during the production of valve spring. Hence, the durability of valve spring will be decreased and the output of the vehicle may be affected. When the said situation occurs, the engine alarm will turn on to alert the driver.

CML has received 6 related cases and already reported to Toyota Motor Corporation (TMC). No associated accident report is received. CML will contact Lexus LS460 and LS600h customers and implement the recall in accordance with TMC's guidance.

For enquiries, please contact our Customer Care Hotline at 2880 1395.

**For media enquiries, please contact:**

Ms. Eunice Pak

Crown Motors Ltd.

Tel: 2880 1361

Fax: 2887 2787

Email: [eunice.pak@crown-motors.com](mailto:eunice.pak@crown-motors.com)

**Premium Outlets:**

Shop A, G/F Harcourt House,  
39 Gloucester Road,  
Wanchai, Hong Kong  
Tel: (852) 2511 9430  
Fax: (852) 2507 2654

G/F Mita Centre,  
552-566 Castle Peak Road,  
Kwai Chung, New Territories  
Tel: (852) 2880 4151  
Fax: (852) 2413 2971

**Service centres:**

Block B & C, G/F Seaview Estate,  
2-8 Watson Road,  
North Point, Hong Kong  
Tel: (852) 2880 1551  
Fax: (852) 2960 1354

G/F Mita Centre,  
552-566 Castle Peak Road,  
Kwai Chung, New Territories  
Tel: (852) 2880 4900  
Fax: (852) 2413 2971



Inchcape