



CROWN MOTORS LTD.

皇冠汽車有限公司
22/F, Citicorp Centre
18 Whitfield Road
North Point, Hong Kong
Tel : (852) 2562 2226
Fax: (852) 2811 1060

Press Release

6th July, 2010

A Recall for Some of the 2000-2001 Toyota Corolla is Needed
To Replace the Gas Generators in the Airbag

Crown Motors Ltd. (CML) has received notice from the manufacture Toyota Motor Corporation (TMC) that some of the Toyota Corolla sold in Hong Kong with a production year 2000-2001 needed to be recalled. There are around 1000 vehicles to be affected.

The recall is due to insufficient amount of gas generators in the passenger side front airbag and hence, it cannot be fully inflated. The protection of the airbag will be relatively reduced. The said issue will not affect the operation of the vehicle.

CML will contact Toyota Corolla customers via letters and implement the recall in accordance with TMC's guidance. No associated complaint and accident report is received regarding this issue.

For enquiries, please contact our Customer Care Hotline at 2880 1395.

For media enquiries, please contact:

Ms. Eunice Pak

Crown Motors Ltd.

Tel: 2880 1361

Fax: 2887 2787

Email: eunice.pak@crown-motors.com



Inchcape
