

CROWN MOTORS LTD.

皇冠汽車有限公司
22/F, Citicorp Centre
18 Whitfield Road
North Point, Hong Kong
Tel : (852) 2562 2226
Fax: (852) 2811 1060

Press Release

21st October, 2010

**Recall on the 2003-2006 Toyota Alphard and Crown,
Lexus RX300 and GS300 Passenger Cars
To Replace Brake System Master Cylinder Cup**

Crown Motors Ltd. (CML) has been informed by Toyota Motor Corporation (TMC) that the Toyota Alphard and Crown as well as Lexus RX300 and GS300 passenger cars (Production Period: 2003-2006) sold in Hong Kong will be recalled for special maintenance. Approximately 2,400 vehicles are affected.

This recall is response to the discovery of insufficient lubricant polymers in the brake fluid, which may cause the brake master cylinder cup to become dry, resulting in a slight leakage of brake fluid. This in turn might activate the brake warning indicator on the meter cluster.

Despite this finding, there is no evidence to suggest that it will adversely affect vehicle operation. We recommend that owners of the vehicles in question notify our staff and schedule a check-up at one of our service centers. CML as well will contact all affected car owners via letter and implement this recall under TMC's guidance. To date, one associated enquiry was reported and no accident report of any kind has been recorded regarding this issue.

For enquiries, please contact our Customer Care Hotline at 2880-1395 during office hours.

For media enquiries, please contact:

Ms. Yen Leung

Crown Motors Ltd.

Tel: 2880 1357 / 9807 1318

Fax: 2887 2787

Email: yen.leung@crown-motors.com