



Crown Motors Ltd.
22/F., Citicorp Centre,
18 Whitfield Road,
North Point, Hong Kong

Press Release

26th January, 2011

**A Recall for Some of the 2007 - 2009 Lexus IS250 is needed
To Rectify Installation of the Fuel Pressure Sensor**

Crown Motors Ltd. (CML) has been informed by Toyota Motor Corporation (TMC) that some of the Lexus IS250 (Production Year: 2007-2009) sold in Hong Kong needed to be recalled. There are around 630 vehicles to be affected.

The recall is due to possible improper installation of the fuel pressure sensor connected to the engine fuel delivery pipe, there is a possibility that, in the course of time, the pressure sensor could loosen and result in fuel leakage. The said issue will not affect the operation of the vehicle. No associated complaint and accident report is received regarding this issue.

CML will contact Lexus IS250 customers via letters and phone, and implement the recall in accordance with TMC's guidance. For enquiries, please contact our Customer Care Hotline at 2880 1395.

For media enquiries, please contact:

Ms. Cassidy Yong

Crown Motors Ltd.

Tel: 2880 1475

Fax: 2887 2787

Email: kassidy.yong@crown-motors.com

Premium Outlets:

Shop A, G/F Harcourt House,
39 Gloucester Road,
Wanchai, Hong Kong
Tel: (852) 2511 9430
Fax: (852) 2507 2654

G/F Mita Centre,
552-566 Castle Peak Road,
Kwai Chung, New Territories
Tel: (852) 2880 4151
Fax: (852) 2413 2971

Service centres:

Block B & C, G/F Seaview Estate,
2-8 Watson Road,
North Point, Hong Kong
Tel: (852) 2880 1551
Fax: (852) 2960 1354

G/F Mita Centre,
552-566 Castle Peak Road,
Kwai Chung, New Territories
Tel: (852) 2880 4900
Fax: (852) 2413 2971

