



**Crown Motors Ltd.**  
22/F., Citicorp Centre,  
18 Whitfield Road,  
North Point, Hong Kong

新聞稿

二零一一年一月二十六日

## **本港出售之部份2007-2009年凌志IS250須召回**

### **以跟進燃料壓力感應器安裝**

皇冠汽車有限公司剛接獲日本廠方通知，於本港出售之部份凌志 IS250 型號汽車(出廠年份為 2007 年至 2009 年)須進行召回，當中涉及約 630 部。

是次召回是由於引擎燃料輸送管上之壓力感應器於安裝時可能出現誤差，長時間後有機會導致壓力感應器與輸送管之間出現滲漏。上述問題不會影響汽車正常行駛，汽車仍能如常運作。皇冠汽車迄今從未接獲任何客戶相關投訴或意外報告。

皇冠汽車稍後會以電話及書面形式聯絡有關型號汽車之客戶，並按照廠方指引進行跟進。如客戶有任何查詢，歡迎致電客戶服務熱線 2880 1395。

#### **傳媒查詢：**

皇冠汽車有限公司

容順盈小姐 (Ms. Cassidy Yong)

電話：2880 1475

傳真：2887 2787

電郵：[kassidy.yong@crown-motors.com](mailto:kassidy.yong@crown-motors.com)

#### **Premium Outlets:**

Shop A, G/F Harcourt House,  
39 Gloucester Road,  
Wanchai, Hong Kong  
Tel: (852) 2511 9430  
Fax: (852) 2507 2654

G/F Mita Centre,  
552-566 Castle Peak Road,  
Kwai Chung, New Territories  
Tel: (852) 2880 4151  
Fax: (852) 2413 2971

#### **Service centres:**

Block B & C, G/F Seaview Estate,  
2-8 Watson Road,  
North Point, Hong Kong  
Tel: (852) 2880 1551  
Fax: (852) 2960 1354

G/F Mita Centre,  
552-566 Castle Peak Road,  
Kwai Chung, New Territories  
Tel: (852) 2880 4900  
Fax: (852) 2413 2971

